



SWSI

Southern Welding Systems International LLC

Welding | Industrial | Safety

International Wholesale Distribution

Contact us for Pricing:

Phone: 281-485-9772 | Fax: 281-485-4386

Email: Sales@swsintl.com | Website: www.swsintl.com

Address: 3908 1st Street Pearland, Texas 77581

BRASS DUAL HOSE BRACES, OVAL 	PART NO.	INSIDE DIMENSION	LENGTH	METAL THICKNESS
	Dimensions In Inches			
	9116	.448 x .890	15/32	.019
	9979	.474 x .943	15/32	.019
	9940-P	.535 x 1.071	3/4	.024
	453	.593 x 1.238	3/4	.025
	453-A	.640 x 1.310	3/4	.025
	454	.700 x 1.325	3/4	.025

PART NO.	FOR HOSE ID	CLAMP ID	BRASS HOSE CLAMPS
Dimensions In Inches			
500	3/16"	7/16"	
501	1/4"	1/2"	
502	1/4"	9/16"	
503	3/8"	5/8"	
504	3/8"	11/16"	
505	3/4"	3/4"	
506	1/2"	15/16"	

HAND-HELD FERRULE CRIMP TOOLS 	PART NO.	DESCRIPTION
	C-1	2 Hole Jaw 5/8" Wide, Use on 3/16", 1/4" Hose
	C-3	3 Hole Jaw 1" Wide, Use on 3/16", 1/4", 3/8" Hose
	C-3B	3 Hole Jaw 1" Wide, Use on 1/4", 5/16", 3/8" Hose
		Crimp with Hand-Grip Pressure:
	C-5	2 Hole Jaw 1/2" Wide, Use on 3/16", 1/4" Hose
	C-5A	3 Hole Jaw 1/2" Wide, Use on 5/16", 11/32", 27/64" Hose
	C-6	2 Hole Jaw 1/2" Wide, Use on 5/8", 11/16" Hose

PART NO.	DESCRIPTION	BENCH FERRULE CRIMPING TOOL
5111-A	Bench Model Hose Crimper Dies need to be ordered separately Dies are available in standard sets listed in Ferrule Table on page 20. Each set includes four segments. Dies are available with plain contracting surface (CD) or special three-ribbed surface (CDR). Sets are ordered by using die numbers in the Ferrule Table. Examples: Plain Die for Ferrule K-K: Order CD-38 Ribbed Die for Ferrule K-K: Order CDR-37	

HEAVY-DUTY FERRULE CRIMP MACHING 	PART NO.	DESCRIPTION
		CR-100



PART NO.	INSIDE DIAMETER	LENGTH	RECOMMENDED HAND CRIMP TOOL	5111-A DIE	
				PLAIN	RIBBED
Listed By Size In Inches * Smallest To Largest ID					
6231	.330	1/2"	C-5A	-	CDR-46
833	.358	1/2"	C-5A	-	CDR-45
622	.380	1/2"	C-5A	-	-
620	.410	1/2"	C-5A	-	-
769	.450	9/16"	C-1, C-5, C-5A, CR-100	-	CDR-41
4750	.478	11/16"	CR-100	-	CDR-41
624	.500	1/2"	CR-100	-	CDR-40
7322	.500	1"	C-3B	-	CDR-39
625	.525	1/2"	C-3B	-	CDR-39
7323	.525	1"	C-3B	CD-38	CDR-38
626	.548	31/64"	C-3B	CD-39	CDR-38
7325	.562	1"	C-3B, C-5, CR-100	CD-38	CDR-37
3588	.564	3/4"	C-3B, C-5, CR-100	CD-38	CDR-37
K-K	.575	31/64"	C-1, C-3B, C-5, C-3, CR-100	CD-38	CDR-37
7326	.593	1"	C-1, C-3B, C-3, C-5	-	CDR-36
J-J	.600	1/2"	C-1, C-3B, C-3, C-5	-	CDR-36
I-I	.625	1/2"	C-3B, C-6, CR-100	-	CDR-35
7327	.625	1"	C-3B, C-6, CR-100	-	CDR-35
H-H	.650	1/2"	C-6	-	CDR-34
7328	.656	1"	C-3B, C-6, CR-100	-	CDR-34
G-G	.675	33/64"	C-3B, C-6, CR-100	-	-
7329	.687	1"	C-3, C-6, CR-100	-	-
F-F	.700	33/64"	C-3, C-6, CR-100	-	CDR-32
7330-B	.718	1"	C-3, C-6	-	-
E-E	.725	17/32"	C-3, C-6	-	-
7331	.750	1"	C-3, C-6	-	-
C-C	.775	17/32"	C-3, C-6	-	-
7332	.781	1"	C-3, C-6	-	-
7333	.812	1"	5111-A**	CD-28	-
7244-A	.875	27/32"	5111-A**	CD-26	CDR-25
5029-A	.900	27/32"	5111-A**	CD-25	-
7242-A	.937	27/32"	5111-A**	-	-
5028-A	.975	27/32"	5111-A**	CD-22	-

See page 19 for listing and descriptions of all Western hand crimp tools and model 5111-A bench tool.

** Use of hand tool is not recommended. Model 5111-A is a heavy-duty bench style ferrule machine.